



Assembly Instructions

Hybrid Connector

- max. 40 mm
- max. 5 mm
- max. 7 mm
4x Power
- max. 5 mm
4x Signal
- crimp (4x Power)
crimp (4x Signal)
- max. 30 mm
- crimp
4x Ethernet contacts
-
- TIP: Put metal ring over conductors between step 5 & 6
- Wrap copper tape to reach 5 mm outer diameter

Shielding braid and copper tape must at least 0,5 mm protrude over crimp area

7.000.900.912

click

crimp

crimp metal ring over crimped area

put shrinking tube over crimped area

⚠ For socket insert strip the shield to max. 12 mm instead of 16 mm

max. 16 mm

max. 4 mm
4x Ethernet