



Assembly Instructions

Straight Connector, Female Thread

1. max. 37 mm
2.

⚠ x
 Contact \varnothing 1 mm = max. 4 mm stripping length
 Contact \varnothing 2 mm = max. 7 mm stripping length
3. crimp
- 4.
5. click
6. click
1x PE click
7.

⚠ Shield is not allowed to touch second O-ring
8. 24 24

✓

✗