



Assembly Instructions

Straight Connector Male/Female Thread

- 1.
- 2.
- 3.
- 4.
- 5.
- 6.
- 7.
- 8.
- 9.

x Pins = 41 mm
Sockets = 37 mm

y Pins = 7 mm
Sockets = 0 mm

z Pins = 10 mm
Sockets = 7 mm

- 10.
- 11.
- 12.
- 13.
- 14.
- 15.
- 16.