



### Assembly Instructions

#### Straight Connector Female / Male Thread, S- / T-Coding

1. 25 mm
2. 10 mm
3. Ferrules are not included  
crimp
4. 5 mm  
5 mm
5. 0,2 Nm
6. code
7. 18  
18
8. 18  
18

Shield is not allowed to touch second O-ring