



### Assembly Instructions

#### Right Angle Connector

1. 80 mm, 55 mm

2.

3. y, max. 4,5 mm

4. x, max. 4 mm

5. crimp

6. crimp

7. click

8. click, code

9. crimp, 7.000.900.906

10. code + position

11. code, position

12.

13. click

14. code

15.

16. 27

17. 24, 25

⚠ x Pins = 7 mm  
Sockets = 0 mm

⚠ y Pins = 10 mm  
Sockets = 7 mm